

# Curved Helium Display Assembly Instructions


Note: Assembly is the same for all sizes of curved Helium displays




1. Assemble bungeed poles.



2. Connect large bungeed poles to corners, matching up stickers.



3. Insert center support pole(s).



4. Pull pillowcased graphic over frame.



5. Zip up the bottom of the graphic.



6. Attach optional light clamps to the top bar in desired locations.  
Tip: It is easier to do this before standing the display up.



7. Connect LED lights to the clamp.



8. Straighten the frame. Have two people hold the sides of the frame, then gently twist until straight.